



# Schröder

## SCULPDOT

ENG	INSTALLATION INSTRUCTIONS	ITA	ISTRUZIONI DI INSTALLAZIONE	NLD	INSTALLATIE INSTRUCTIES	DAN	INSTALLATIONSVEJLEDNING	HUN	TELEPÍTÉSI ÚTMUTATÓ
DEU	INSTALLATIONSANLEITUNG	POL	INSTRUKCJE MONTAŻU	RUS	Инструкции по установке	RON	INSTRUCȚIUNI DE INSTALARE	CHI	安装说明
FRA	INSTRUCTIONS DE MONTAGE	SPA	INSTRUCCIONES DE INSTALACIÓN	POR	INSTRUÇÕES DE INSTALAÇÃO	SWE	INSTALLATIONSANVISING	UKR	Інструкції з монтажу
SRP	UPUTSTVA ZA INSTALACIJU	AR	تعليمات التركيب						



220-240V  
50Hz








A	199 mm
	7.83 in
B	240 mm
	9.44 in
C	213 mm
	8.42 in

D	141 mm
	5.55 in
E1	160 mm
	6.29 in
E2	140 mm
	5.51 in
F	170 mm
	6.69 in





A	60 mm
	2.36 in
B	25 mm
	0.98 in
C	213 mm
	8.42 in

D	150 mm
	5.90 in
E	105 mm
	4.13 in
F	67 mm
	2.63 in
G	9 mm
	0.35 in



220-240V 50-60Hz

1 - 2.5 mm



L = 1  
N = 2

L = 1  
N = 2  
PE = ⊕





~~IP66~~

~~IP66~~

IP66

DMX


M12 A-CODE  
4/5 WAY




1 = GND (DMX Common)  
2 = data -  
3 = data +  
4 =  
5 =

DALI

M12 A-CODE  
4/5 WAY



1 =  
2 =  
3 = DALI  
4 = DALI  
5 =



SCULP 150

